

MONUMENT RECORD
State of Indiana - County of Monroe

Section: 35

Township: 7 North


Range: 1 East

Corner ID: Polk Q-23

Monument Description & Remarks: 3" Aluminum cap. Survey Sign 5ft above ground at pt. D

References On File: Kent Anderson survey notes (1983); Robert Stone Forest Service survey, land corner record and Edmund O. Farkas survey, Robert P. Nellis (1993), on file in Surveyor Office

RECOVERY TIE DRAWING
Field Book 33 Page No. 32
Field Book 41 Page No. 69



A - 3" Aluminum cap
B - S 86° W 1.90' to metal
fence post
C - S 80° W 16.56' to MAG
in 22" Black Oak
D - N 49° E 12.99' to Bearing
Sign on 22" Pignut Hickory
E - S 53° E 26.04' to Bearing
Sign on 18" Black Oak

Not To Scale
Compass Bearing Magnetic North

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code; and the above data is given under my hand and seal this 10th day of October, 2000.



Administered by the Monroe County Surveyor Review Board

Date: 4-7-2009

Index No. IX 17
(Alphabetical - Numerical)

LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7100-74 (Rev. 5/80)

826-531

T. 7 N R. 1 E 2nd Mer. N.F. Hoosier County MONROE State INDIANA
1/4 Corner common to sections 34 35 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

(Wood post, stone, pile of stones, pipe, etc.)

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Where filed or recorded _____

Monument _____

(Original, concrete post, iron rod, etc.)

Evidence of Subsequent Corner Restoration Found

Year of search 1984 By _____

Bearing Trees, Reference Objects


Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects



Sketch

○ Corner ☒ F.S. Land

At time of search:

1. Did you have the record description?

Yes _____ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
etc. _____

3. Man hours spent in search _____

4. Do you think additional search might
recover evidence? Yes _____ No _____

5. Signature

Robert J. Stone

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any.

CORNER SETS ON W. EDGE OF AN OLD N-S
FENCE MOUND

Perpetuation Record

Monument and accessories established. Include brief description of area.

SET 30" ALUMINUM CONCRETE FILLED PIPE W/ ALUMINUM
CAP 3" DIA. ~~FOR~~ FOR CORNER MONUMENT. ON
SOUTH SLOPE SOUTH EDGE OF RIDGETOP APPROX.
50' S. OF OLD WOODS ROAD. SET THE
FOLLOWING BEARING TREES:

B.O.	HICKORY	B.O.
14"	18"	10"
N72°E	S39°W	N53°W
17.3'	14.0'	26.9'

Certified corner restoration certificate prepared:

Yes _____ No _____

Filed in county records at _____

Date _____

County Document No. _____

Identified on aerial photo No. _____

Which is filed at _____

Index No. X-17
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)R9-7150-4 (Rev. 6/13/67)
GPO 806-924T. 2N S. 1E Mer. 2nd N.F. No. 3127 County Monroe State Ind.
W Section Corner common to sections 34 35 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed. 1814
Original monument Wood Post
(Wood post, stone, pile of stones, pipe, etc.)

Original Evidence Found

Year of search 1972 By H. Dorton B. Apnes
No

Bearing Trees

Species	<u>Hickory</u>	<u>W 024</u>	
Diameter	<u>6"</u>	<u>12"</u>	
Bearing	<u>S 54 E</u>	<u>N 6 W</u>	
Distance	<u>22 1/2</u>	<u>27 1/2</u>	

Subsequent Corner Restoration

Year surveyed. _____ By _____
Where filed or recorded _____
Monument _____
(Original, concrete post, iron rod, etc.)

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____


Corner monument

T2N R1E Secs 34 & 35

X17

1/4





Sketch

☐ Corner ☒ F.S. Land

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____
 Object _____
 Record distance _____
 Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Talked to local residence. They know of no stone ever been in this location. Bob is the owner of the S. Acres in the SE 1/4 NE 1/4 of Sec. 34.

At time of search:

1. Did you have the record description?

Yes ☒ No _____

2. How was search area located?

Pacing, chaining, photos, maps,
 etc. maps, photos

3. Man hours spent in search 1 1/2 hr.

4. Do you think additional search might recover evidence? Yes _____ No ☒

5. Signature J. Deaton

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

Dutch Ridge
road is 38 rods West of Corner - Did chain from road and found no evidence of corner stone.

Certified corner restoration certificate prepared: Yes _____ No _____

Filed in county records at _____ Date _____ County Document No. _____

Identified on aerial photo No. _____ Which is filed at _____